DescriptionCorrest Instrumentation Consultancy & DesignProcess Instrum

NUSTAR ENERGY LTD

FUNCTIONAL SAFETY COMMITTEE

MINUTES OF MEETING

NOVEMBER 2016

Rev	Date	By	Checked	Approved	Description	Client Ref.
А	23.11.16	D. R. Ransome		DRR	Issued as Pro-Forma for Meeting	
В	01.12.16	D. R. Ransome	Romme	NuStar Safety	Issued following meeting	
			X Mansone	Committee		Document No.
						_
						NU001115_MIN
		IF NOT SIGNED 7	THIS DOCUMENT IS UP	VCONTROLLED		

Contents

1	REVISION HISTORY
2	ACTION STATUS4
2.1	Actions outstanding from Safety Committee Meetings4
2.2	Actions outstanding from Functional Safety Assessments9
2.3	HSE Visits
3	SAFETY COMMITTEE MEETINGS24
3.1	Minutes of Previous Meeting25
4	MANAGEMENT OF FUNCTIONAL SAFETY
4.1	SIS Performance including any maintenance, failures, activations and false alarms26
4.2	Lifecycle Documentation29
4.3	Functional Safety Management System31
4.4	SIS Testing, planning, results, data collection and analysis
4.5	Training requirements and roles and responsibilities of employees and contractors38
4.6	Review of organisation and resources
4.7	Outcome of Functional Safety Assessments and Outstanding Action status
4.8	Review of any management of change or modifications to the systems
4.9	Review of any HSE or other agency visits41
4.10	Review of any changes in the standard or competent authority guidelines43
4.11	Review of competency requirements43
4.12	Review of independent Instrumented Safety Functions43
5	ACTIONS ARISING FROM THIS MEETING44
6	DATE OF NEXT MEETING50

Appendices

E/550 Reports

These reports are now contained within a section of NuStar ASANA Faults and Activations



Meeting Date 30th November 2016

1 REVISION HISTORY

Rev	Description
А	Issued as Pro-Forma for meeting.
В	Issued following meeting.




P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 3 OF 50

2 ACTION STATUS


- 2.1 Actions outstanding from Safety Committee Meetings
- 2.1.1 Actions outstanding from Safety Committee meeting October 2015.






P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 4 OF 50

2.1.2 Actions outstanding from Safety Committee meeting 5th April 2016.





P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 5 OF 50










David Ransome B Apr at 09:58 Arrange a date for Eastham training





DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 7 OF 50





P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 8 OF 50

2.2 Actions outstanding from Functional Safety Assessments


The following list details all the FSA's which have been conducted – the greyed out and ticked FSA's indicate all actions have been completed and the FSA is closed.

		\star FSA Status 🗸					
		List	Conversations	Calendar	Progress	Files	
Add	d Task				View: All Ta	sks 🗠	
\odot	Amsterdam FSA 1 - Tank Overfill SIS						
0	Belfast FSA 4				31 Mar, 201	5	
	Belfast FSA 5 - Magnetrol Tanks 46 & 47						
Ø	Belfast FSA 5 - Magnetrol Tanks 4, 5 & 12						
	Clydebank FSA 4						
	Clydebank FSA 5 - Magnetrol Tanks 7 & 9						
0	Clydebank FSA 5 - Tank 4 LoC						
0	Eastham FSA 4				31 Mar, 201	5	
	Eastham FSA 5 - Dockline 05 H & J Slab						
	Eastham FSA 5 - Dockline 05 D Slab						
0	Eastham FSA 5 - Shell Modifications						
0	Eastham FSA 5 - Chloroform						
0	Eastham FSA 5 - Radar Ranging						
	Grangemouth FSA 3						
	Grangemouth FSA 4						
	Grangemouth FSA 5 - Tanks 101, 102 & 103						
0	Grangemouth FSA 5 - In-Scope Tank Modific	ations					
	Grays FSA 4						
	Grays FSA 5 - New Red Dockline						



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 9 OF 50


2.2.1 Actions outstanding from Belfast FSA 4



David Ransome changed the due date to 30 Dec. Vesterday




P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 10 OF 50






2.2.2 Actions outstanding from Belfast FSA 5 – Magnetrol Tanks 4, 5 & 12





P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 12 OF 50 2.2.3 Actions outstanding from Eastham FSA 4

The following outstanding actions were reviewed and updated at the October 2015 Safety Committee Meeting.






P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 13 OF 50

	David R	30 Dec	006	ð
Eas	tham FSA 4			
\oslash	review	ed and ens	entation to b ure that it re installed sy	flects
	Description	Ĩ		
	David Ranso	me created task. 5 Ma	r, 2015	
	David Rans	some 5 Mar, 2015 at 1	6:57	Q
		ome on Thursday N IU231 - Eastham FSA	ar 05, 2015 02:15 PM 4	;
		me assigned to you. 1 me changed the due da	8 Mar, 2015 Ite to 25 Mar, 2015. 18 N	lar, 2015
	David Ranso	me changed the due d	ate to 24 Nov, 2017. 7 No	vo
	David Ranso	me chanced the due da	ite to 30 Dec. Yesterday	




2.2.4 Actions outstanding from Eastham FSA 5 – Shell Modifications






P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 15 OF 50

2.2.5 Actions outstanding from Eastham FSA 5 – Chloroform









There is a difficulty with this modification in that the logic solver cannot handle the analog inputs. It is intended to complete this FSA based on determination of LoC as progress will be as and when the logic solver is updated, and this will require a further FSA 5.




2.2.6 Actions outstanding from Eastham FSA 5 – Radar Ranging

simon.hunter 🗇 Dec 💿 🕞 🔊 … 🤇
tham FSA 5 - Radar Ranging
1 - MoC for this modification to be completed.
Description
David Ransome created task. 26 Feb David Ransome added to Eastham FSA 5 - Radar Ranging. 26 Feb David Ransome assigned to simon.hunter@nustarenergy.com. 26 Feb David Ransome changed the due date to 4 Mar. 26 Feb
David Ransome changed the due date to 17 Nov, 2017. 7 Nov

David Ransome changed the due date to 9 Dec. Yesterday



2.2.7 Actions outstanding from Amsterdam FSA 1





2.2.8 Actions outstanding from Clydebank FSA 5 – Tank 4 LoC

b	David F Tomorrow
Ciye	lebank FSA5 - Tank 4 LoC
I	FSA 5 Action 1
	The current SRS NU221003_RPT details the SIS for all of the terminal's storage tank SIF's. It will be necessary to revise and update this in line with the modification.
	Dave Regan created task. 23 Nov Dave Regan added to Clydebank FSA5 - Tank 4 LoC. 23 Nov Dave Regan assigned to Dave Regan. 23 Nov
	David Ransome assigned to David Faulkner. Yesterday David Ransome assigned to Dave Regan. Yesterday David Ransome changed the due date to 9 Dec. Yesterday David Ransome assigned to David Faulkner. Yesterday David Ransome changed the due date to Tomorrow. Yesterday
	David Ransome Vesterday at 10:36 Append revised SRS for FSA review
dp	David Relisonic (discourse) and a
dp Clyr	Append revised SRS for FSA review
dp Clyr	Append revised SRS for FSA review
dp Clys	Append revised SRS for FSA review
dp Ciya	Append revised SRS for FSA review darren.peck
do Clyn O	Append revised SRS for FSA review darren.peck Due Due Due Solution (a constraint) of the constraint



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 20 OF 50


1000	darren.peck (Tomorrow ()()()()()()()()()()()()()()
Clyd	ebank FSA5 - Tank 4 LoC	
Ø.	FSA 5 Action 3	
	Ensure the P&I D's are in accordance with the proposed installed system.	
	Dave Regan created task. 23 Nov Dave Regan added to Clydebank FSA5 - Tank 4 LoC. 23 Nov Dave Regan assigned to you. 23 Nov Dave Regan assigned to darren.peck@nustarenergy.com. 23 Nov	
	David Ransome changed the due date to Tomorrow. Yesterday	
0	David Ransome Vesterday at 10:45	0
	P&I to be uplaoded	
-	A AAAAAAAAAAAAA	
Carol		
Ciy	debank FSA5 - Tank 4 LoC	
Ciy Ciy	a 00000	
Civ Civ	debank FSA5 - Tank 4 LoC	
© (1) (2) (2) (2) (2) (2) (2) (2) (2) (2) (2	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to	
ay Ø	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS	
	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf Deve Regan created task: 23 Nov Deve Regan added to Clydebank FSA5 - Tank 4 LoC: 23 Nov Dave Regan assigned to David Faulkner: 23 Nov	Q
	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf Deve Regan created task: 23 Nov Dave Regan added to Clydebank FSA5 - Tank 4 LoC. 23 Nov	Ð
	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf Deve Regan created task: 23 Nov Dave Regan added to Clydebank FSA5 - Tank 4 LoC. 23 Nov Dave Regan assigned to David Faulkner. 23 Nov David Faulkner @ attached Sunday at 10:21 NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf	Q
	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS NU211003_DWG_B - CL-SIS1 Schematic Overview.pdf Deve Regan created task: 23 Nov Dave Regan edded to Clydebank FSA5 - Tank 4 LoC: 23 Nov Dave Regan essigned to David Faulkner, 23 Nov David Faulkner @ attached Sunday at 10:21	Ð
	debank FSA5 - Tank 4 LoC FSA 5 Action 4 The schematic overview drawing NU211003_DWG to beupdated as part of the SRS NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf Dave Regan created task: 23 Nov Dave Regan added to Clydebank FSA5 - Tank 4 LoC. 23 Nov Dave Regan assigned to David Faulkner. 23 Nov David Faulkner @ attached Sunday at 10:21 NU211003_DWG_8 - CL-SIS1 Schematic Overview.pdf David Faulkner assigned to Dave Regan. Sunday	0

David Ransome changed the due date to 9 Dec. Vesterday




P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 21 OF 50



P & I DESIGN

2.2.9 Actions outstanding from Grangemouth FSA 5 - In Scope Tank Modifications



2.3 HSE Visits

No SIS related HSE visits since last safety meeting.

P & I DESIGN

P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 23 OF 50

3 SAFETY COMMITTEE MEETINGS

The object of this committee is for NuStar Energy Ltd to organise and control the Safety Instrumented Systems throughout their UK facility to ensure satisfactory operation, functional safety and compliance with the international standard BS EN 61511.

Date of Meeting	30/11/2016					
Location	NuStar Belfast Terminal					
	Present					
Name	Company & Position	Competence				
Simon Hunter	NuStar Eastham – Terminal Engineering Manager	Mechanical Engineering BEng (Hons) with over 15 years' experience as an Engineer on Oil Storage Terminals. Five years at NuStar managing the Engineering Maintenance, Inspection and Testing.				
Darren Peck	NuStar UK - EC&I Engineering Manager	Over 20 years' experience in the petrochemical process industry ranging from design through to installation and commissioning.				
Yvette Davis	NuStar UK - Senior Manager for HSE	Over 17 years' experience in managing HSE in TT COMAH sites, 8 years' experience in Fuel Storage Terminals, managing both Process and occupational safety aspects.				
David Ransome Chair	P & I Design Ltd – Consultant	Chartered Engineer and a Fellow of the Institute of Measurement and Control with over 40 years' experience in the Chemical and Process Industry, specialising in High Integrity Protection Systems and Safety Instrumented Systems. Registered Functional Safety Engineer.				
David Faulkner	P & I Design Ltd – Engineer	Involved in the maintenance and commissioning of Process Plants, Storage Facilities and Safety Instrumented Systems for over 15 years. Experience includes on-shore systems, including high integrity protection systems. A qualified Functional Safety Specialist.				
Paul Price	NuStar Eastham Site Engineer	Mechanical Engineering BEng (Hons) with over 8 years' experience as a mechanical Engineer. Two year's experience on Oil Storage Terminals.				
Neil Woodley	Engineering Manager Belfast & Clydebank	Hons degree in Chemical Engineer, over 20 years working for NuStar on various sites. Currently Engineering Manager for Belfast & Clydebank				

P & I DESIGN

P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 24 OF 50

3.1 Minutes of Previous Meeting

The minutes of the previous meeting NU00114_MIN Revision C were reviewed; some actions remain incomplete. See Section 2 of these minutes.

Actions within an FSA are to be controlled within the relevant FSA. Outstanding actions from FSA's are detailed in Section 2 of these minutes.



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 25 OF 50

4 MANAGEMENT OF FUNCTIONAL SAFETY

4.1 SIS Performance including any maintenance, failures, activations and false alarms.

See ASANA for E/550 reports.

4.1.1 Belfast

LIKEFOOT - Tank 29 - 07.05.13 - Liquiphent	
UKBECK2 - Twok 27 - 10:08:13 - Liquiprovii	
CKBF003 - Tarox 34 - 20.08.13 - Novelenser	SL) Carros Fail
💿 UKBF004 - Tarik 5 - 01.0634 - Rader	Middinana
UKBF005 - Tanic 21 - 18.05.95 - Liquiphant	SD Comp Fut
UKEFOOS - Tank 30 - 05.0835 - Liquiphans	(SO) (Comp Fail)
UKBF007-Tarik 6 - 12.08.15	(55) (Oxendum)
UKBF008 - Tarak 50 - 15.00.35 - Nivotester	(SD) (Spanne)
UKBF009 - Tank 50 - SEDE35 - Uquidhant	(SD) (Comp Fee)
UKBF010 - Tank 18 / 15.10.15 / Cigulphint	(ID) Competer
URBFOTI - Tank 19 - 10.11.15 - Nivotester	(ID) Come Fall)
OKBF012 - Tanie 49 - 2112.05 - Lipplyheett	(Com 74)
UKBF013 - Tank 14 - 04.0136 - Ligisphant	(SD) (Samp Rul)
UKEFCIA - INKA SIS - PSU	(SD) Comp Full
UKBF015 - Tank 08 - 05.0436 - Liquiphant	🗐 🥌 10 bec 🧌
UKBF016 - Tank 17 - 14.06.16	(Dimani) 9 Dec 🖗



4.1.2 Clydebank

-		14		67			2
C	١v	Ø	e	b	a	n	k
-	х				-	_	

IJKCLODE - Time 7 - 27/03/34	(SD) (SMIDIA)
UMCL007 - Tank 2 - 29.0434	SD Como Pat
LIKCLODB - Trime S - 06:05:34	(2) (2011)
UMCL009 - Taris 9 - 22.0534	(SS) (SSitua)
O URCLOID - Tains 9 - 20.06.14	(incluse)
LINCLOT - Tanic B - 20.06.54	(SD) (Splittum)
OKCL012 - Tank 7 - 03 0934	(Status)
UKCL013 Tarik B 24.134	(5D) (SLAMAAA)
LIKCL014 - Tenti 9 - 16/05/35	(Come Feit)
URCL015 - Tank 2 - 28.0434	(DD) (Canad Fail)
1.00CL016 - Tanic 2 - 06.05.75	(Come Fit)
Queen L017 - Tarsk 13 - 36:395.35	50 (Circle)
UKCL018 - Tank 1 - 1108.15	(53) (Bpinionin)
OKCL078 - Twick 1 - 23.0635	(C) Common
LIKCL020 - Tarea 2 - 02:015 - Velve Fault	(EO) (Comunic)
UKCL021 - Tank 7 - 231135 - Montenance Activity caused fault	(III) (Maintoone)
UKCL022 - Tank 1 - 05.0436	(10) (11) 30 Dec 🕼
UKCL-023 - Tank 7 - 19.04.16	💷 📀 9 Dec 🏟

4.1.3 Eastham

Eastham:	
UKEHD04 - 7K01 - 28.0334	(50) (Solice)
UKEH005 - TKR3 - 00.0634	(SD) (Starting)
UKEH006 DL02 - 15/10.14	GD Comptab
UKEH007 DL31 (Not SISL-20.0215)	(SD) (Sump Se)
UKEHD08 PUZ Fell + 02.03.15	(B) Constant
UKEH009 - Tank 18 - 20.05.16	(SD) (Sperature)
🟐 UREHOTI - Tanlı 60 - Rədər - Sporious Alam in amply tarik - 26.1015	
UKEH012 - DL02-EEV - Dockline velve closed but no indication was received as constallure 301015	(D) Constat
UKEH013 - Ténik 247 - IHLA seems to be set too low in the tank? - 08.02.16	SO Comand
UKEH-014 - Tanik 42 - 05.05.16	Constant Constant (
UKEH015 - Tank 60 - 10.06.16	(E) Saussa 9 Dec A
UKEH016 - Tank 30 - 22.0736	(III) (Sincara) 9 Dec 🗐
UKEH017 - Tenk 30 - 05.0836	(ED) (Staroos) 9 Dec (
UKEH018 - Tank 56 - 26.0936	(1) 200 Carros 9 Dec (
UKEH019 - Tank 56 - 29.0936	GD Source 9 Dec A

P & I DESIGN

P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 27 OF 50

4.1.4 Grangemouth

			1000
Gra	nae	mo	utn:

CINORROD2 - 15649 - 10.01.14	(Demted) (Disasteria)
CIREMODS - TRS4 -10.0794	(CO) (Second
OKOMOOG Tamii 43 - 20.0055	(SB) (Systemat.)
CIRI2MID07 - Tirriv B1 - OB.06.35	(SD) (Maintana)
UKEM008 - #5V - 12.08.15	
UKEMOR8 (Duplication) Nol - Tank 87 - 201036	(B) Comp Au
CMI3M009 - Tanic 89 - 15.02.35	(S) (Station)
UKSM010 - Derv Receipt Line - '20.02.%	(SD) (Obmidenti)
💿 URIDMOTE - PIDA Import Line	(Constant)
CUESNO12 - MCICO1	(Comptee)
UNGMOH3 - Tarric 881 - 31.0336	(52) Southur)
💿 Сметалота - Тапи 53 - 21.01316	(Souther)
UKGM-015 - Tanix 54 - 11.05.16	(50) (Sourney, Toeranow
UKGM016 - PILZ PLC Output module failure	6) cmp A

4.1.5 Grays

💿 Lacandon Tunk III - 073034	(ED) (Epuktion
C UKGROO4 Tank 18 - 03.10.14	(30) (Stimuta)
UKGR005 - Tank 44 - 27.07.16	(CO) Studinos 9 Dec 🗐



4.2 Lifecycle Documentation

The on-line documentation system controlled by P & I Design Ltd is now fully operational and is currently being populated with all NuStar Energy documentation.

The uploading of documentation has been ongoing over the last few months, but is now well underway. Some difficulties have been encounted in ensuring the correct third party documentation is the current and latest versions.


The client interface has also been changed to simplify the method of entering the on-line documentation system. The procedure is now:

Utilising an internet browser go to:

1. <u>www.pidesign.co.uk</u>



2. Click on the top banner – Cloud Documentation



3. Click on – Login to documentation system



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 29 OF 50



4. Enter Username and Password

Username is: Safety Committee - The user name and password were issued at the Safety Committee meeting.

Click on Log In

NuStar	
Nustar Safety Committee – Documentation Click on links bolow for more details	
Nustar Safety Committee Site Index	
De-Ine documentation presentation	
NU001002_RPT - UK Terminate Safety Instrumented Systems Policy and Liferrycle Activities	
NUCO1114_A_MIN - Functional Safety Committee Minutes of Meeting April 2016	
NU001114_B_MIN – Functional Safety Committee Misulas of Meeting April 2016	
NUb01113_B_MIN - Functional Safety Committee Minutes of Meeting October 2018	
NU001112_B_MN - Functional Safety Committee Minutes of Meeting March 2015	
NU0011111_D_MIN - Functional Safety Committee Minutes of Mooring September 2014	
NU001109_C MIN – Functional Safety Committee Minutes of Meeting September 2013	
NU001107_C_MIN - Functional Safety Committee Minutes of Meeting March 2013	
NU001104_D_MIN - Functional Safety Committee Minutes of Meeting September 2012	
NU001102_C_MIN - Functional Safety Committee Minutes of Meeting March 2012	

5. Click on required document or manual



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 30 OF 50 4.3 Functional Safety Management System

Dave Ransome outlined that IEC61511: 2016 has strengthened the requirements related to the of management of SIS, and as such the following will need to be modified or created:

4.3.1 Policy & Lifecycle Activities Document

Following the original issue of the Policy and Life-cycle activities document, which has previously been issued, it is now necessary to modify this document in line with IEC61511: 2016.

ACTION 2016 – 09: Update Policy Document in line with changes resulting from IEC61511: 2016 Completed

4.3.2 Functional Safety Management System (FSMS)

The SIS requires a FSM system, which includes auditable procedures and records, for the following:

- Competency management;
- HRA and SIL determination;
- SIS Validation, verification and proof testing;
- Operation and Maintenance activities;
- Management of Change;
- Functional Safety Assessments and audits;
- Monitoring of the SIS performance and corrective actions;
- Configuration Management;
- SIS Security.

The safety committee discussed each of the above, see below:

4.3.2.1 Competency management

The requirements:

Persons, departments or organisations involved in SIS safety lifecycle activities shall be competent to carry out the activities for which they are accountable;

A procedure shall be in place to manage competence of all those involved in the SIS life cycle. Periodic assessments shall be carried out to document the competence of individuals against the activities they are performing.

NuStar employee competence system is managed through the Safety Management System. Where necessary suppliers of SIS related systems are asked to demonstrate their competency systems to NuStar.

4.3.2.2 HRA and SIL determination

Hazard & Risk Assessments have been carried out and are reviewed as necessary in consideration of Functional Safety Assessment 4 & 5. SIL determination is conducted by third party companies during the design phase of the SIS.

P & I DESIGN

4.3.2.3 SIS Validation, verification and proof testing

SIS Validation, verification and proof testing is performed at the required life-cycle phases. Through the safety committee these activities are regularly reviewed and if gaps are identified then improvements are made.

4.3.2.4 Operation and maintenance activities

NuStar have SAP which is utilised for maintenance activities. SIS equipment is uniquely identified within SAP. Operators are aware of their responsibilities through training and when issues arrive, such as faults or activations they utilise the E/550 form to report the problem. Override procedures of the SIS are well defined and require authorisation before being initiated.

4.3.2.5 Management of Change

NuStar Energy have included management of change to the SIS within their company based MoC procedures and the company recognises the need for Functional Safety Assessments when a modification to the SIS is required. The company has to date conducted or have in progress 12 - FSA 5's.



4.3.2.6 Functional Safety Assessments and Audits

4.3.2.6.1 Assessments

Functional Safety Assessments are conducted at the relevant life-cycle phase. To date the SIS have been subjected to:

FSA 1 - 1 (This is for a new SIS at Amsterdam) FSA 3 - 1 (For a completely revised SIS at Grangemouth) FSA 4 - 5 (One at each of the UK terminals, planning for future FSA 4 is controlled by the safety committee) FSA 5 - 12 off

The company now recognises that FSA are to be conducted at the relevant life-cycle phase.

FSA 4's were conducted in 2011, the company have been pro-active in the monitoring and development of the SIS through the Safety Committee. FSA 4's have not been conducted, as originally intended in 2016, they have been delayed awaiting the issue of IEC61511:2016. It is the intention of NuStar to refine and develop their FSMS and conduct an audit on it. Furthermore, it is intended to perform a FSA 4 at each terminal throughout 2017

4.3.2.6.2 Audits

The purpose of the Functional Safety Audit is to review SIS procedures and records to determine whether the functional safety management system (FSMS) is in place, up to date, and being followed.

Including:

A review of all the SIS policies and procedures;

An audit that personnel are following the procedures and that the latest version of the procedures are used.

Audits are typically carried out by an independent person familiar with carrying out audits, such as a quality manager, with obvious reference to IEC61511. Where gaps are identified, improvements should be made.

The Safety Committee felt that it would be appropriate for their QA auditors to audit to audit the FSMS. However, training in IEC61511 would need to be provided to them prior to the audits.

ACTION 2016 – 10: Arrange IEC61511 appreciation training for auditors.



4.3.2.7 Performance Monitoring

Procedures shall be implemented to evaluate the performance of the SIS against its safety requirements to:

- identify and prevent systematic failures;
- assess whether reliability parameters of the SIS are in accordance with those assumed during the design;
- define the necessary corrective action to be taken if the failure rates are greater than what was assumed during design;
- compare the demand rate on the SIF during actual operation with the assumptions made during risk assessment when the SIL requirements were determined.

NuStar Energy have procedures and forms in place for the monitoring of all activations, failures, maintenance activities and modifications to their SIS. The safety committee reviews all activations, spurious trips at their 6-monthly meeting. Further enhancements are in place to provide performance monitoring against the designed pdf, SIL, spurious trip rate and the demand rate.

The proposed database to compare installed SIS reliability parameters is being developed by P & I Design Ltd with a view of not only containing NuStar Energy SIS components, but also other client's data to provide all clients with a greater volume for assessment. Client confidentiality is obviously respected and both individual client installed component data and the wider community data can be provided. Examples of the intended output is shown below:

Co	nponents							
Componenti	0	li					Add a new	
Carrier and a second		1				-	Cumponent	
Element Sub	dystem	Senso	r			×		
Technology		Vibro	nics					
Manufacture	H) (Endre	ss & Hauser					
Model		Liquip	hant			- 9		
Model Series		1						
Manufacture	ers Claimed PFD	1.50E	-03	1				
Manufacture	ers Claimed SIL	1			Save			
Manufacture	ers SFF	0.95		1	Save & Close			
Prouf Test In	terval	8760	5					
Components	addedi	hi						
Comp	onent + Elemen	:Sut +	Technology ·	Manufactur +	Model +	Manufactu	rers Claimed PFD +	Manuf
	1 Sensor		Vibronics	Endress & Hau:	Liquiphant	and the second	0.0015	
2	2 Sensor		Nivotester	Endress & Hau	Nivotester		0.0015	
Ŧ	3 Logic Sc	dver	Vibronics	Vega	Vegaswing 63		0.00011	
*	4 Final El	ment	Vibronics	Vega	Vegator 636		0.00047	
æ	5 Logic Sc	dver	Radar	Vega	Vegaplus 61		0.00157	
18	6 Final Ele	ment	Isolator	Peppert & Fuch	KFD2-CRG2-Dx		0.000394	
a .	7 Sensor		Radar	Endress & Hau	Radar		0.00011	
+	8 Logic Sc	duer-	Displacer	Magnetrol				

P & I DESIGN

P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 34 OF 50

omponentID Manufactu	rer	Mode	el	Device Type			
2 Endress &	Hauser	Nivo	tester	Nivotester	Nivotester		
Number in Use:	101						
Hours in Use:	2.91E+06						
Years in Use:	332.5						
Number of Failures:		Failure rat	tes /hr:	Dangerous Undete	ected Failures:		
Safe Detected:	2	λSD:	6.87E-07	FailureDate Re	port Link		
Safe Undetected:	2	λSU:	6.87E-07	22/08/2016 <u>RP</u>	TS\Report 123		
Dangerous Detected:	3	λDD:	1.03E-06				
Dangerous Undetected:	1	λDU:	3.43E-07				
Fotal Failures:	8	λD:	1.37E-06				
MTTR (Hrs):	3.29						
SFF:	0.875		Manuf	facturer's Claimed SFF:	0.87		
Proof Test Interval (Hrs):	8760						
tce (Hrs):	1098.3						
PFD avg:	1.51E-03		Manuf	facturer's Claimed PFD:	1.50E-03		
SIL Capability:	2		Manuf	facturer's Claimed SIL:	2		

•The probability of failure on demand has been calculated as higher than is claimed by the manufacturer. You must check all systems which use this component to check they have the appropriate SIL.

All-Fallacies	1											
initiary(#ID	· Competent	- Clarment Sul +	Manufacturer +	Technology +	Model - Model Serie -	Techty	- 95	+ Duty	··· Chard	W TashareDate - Description -	Report link - Type +	Mittil Hea:
	30	E.Sensol	Endress & Heuser	Vibromes	Liquiphant	Balfast	Overfill	Taek 40	citent2	04/04/2016 Report 3537	renshreport 5 Safe Detected	
	32	1 Seroor	Endress & Henser	Vibrorries	Liquiphare	Beilint	Overfill	Task 41	Citert2	12/04/2015 Report 2003	Safe Detected	
	124	2 Secept	Endmin & House	Alsobertier	Nexterter	Beitett	Overfill	Tank 30	Chient2	12/05/2016 Report 3343	Safe Undetects	
	32	1 Sensor	Endress & Hauser	Vibronics	Liquiphare	ilelfast:	Overtill	Tank 48	Client2	15/08/2016 Report 1234	Safe Undetect	
	39	1 Sensor	Endress & Hiluson	Vibronics	Liquiditurit	Beifatt	Overfill	Tack 45	0100.112	15/08/2016 Report 3212	Disoperest fiel	
	34	1 Sensor	Endress & Hauter	Vibronics	Dquiphare.	Delfust.	Overfill	Tank SD:	Climit2	15/06/2016 Report 1234	TETTINAPORT 1. Dangerous Uni	
	122	7 Settool	Endress & Hauser	Nactoriter	Nextexter	Gelfatt	Overfiit	Tank 43	Climit2	16/08/2015 Report 5340	Davigerous Del	
	342	2 Sensor	Endress & Hauser	Nivotester	NAstecter	Belfatt	Overtill	Tark 1	CRent2	04/08/2016 Re	Dongerous Det	
	31	I Sérsel	Endness & Hauser	Vibronics	Liquenare	melfast.	overtit	Tata 41	chentz -	1h/08/2011 Report 3368	Safe Detected	
	20	I Serior	Englass & Hauser	Vibronies	Dquiphant	Delfest.	Overfill	Teskar	Client3	37/00/2016	Safe Underland	
	343	5 Logic Solver	Wege:	Sadar	Vegaphulli	Belfact	OverTemp	Tank34	Client(2	18/00/3018	Sate Detected	
	-34	1 Sensor	Endress & Houser	Vibronics	Uquiphert	Belfast	Overtill	Tark 18	(Deit)	22/08/2016	Safe Detected	
	18	1 Sensor	Endrets & Hauter	Villeonies	Liguphant.	04Hat	Overfilt	Ta19.25	clieit2	22/08/2016	Safe Undetech	
	23	L Sensor	Endress & Hauter	Vibrarrics	Lispatisharit	Belfint-	Overfill	Tatk 30	Client2	22/06/2016	Safe Detected	
	36	1 Service	Cratrics II. Heurer	Viennus	Lepatentant	Builtant.	Overtili	Tank 23	Client2	22/06/2015 Report 1200	RPTS/Report 1 Dangetous line	
	125	2 Sensor	Endress & Houser	Nivotester	Nivotester	Belfast	Overtill	Tank 31	Client2	22/08/2016	Safe Detected	
	334	2.561501	Endress & Hauser	Nivotester .	WADDESER!	Belfatt	Overfill.	Tarik 10	Climit2	38/08/2010	Sole Detected	
	154	Z Sensor	Endress & Hauser	Nottenter	Niaotester	Belfeit.	Overfill	Tank 45	Client2	22/08/2016 Report 4524	Safe Undetect	

Claiment Spin-A	Syttem: Manufactuber	Martin	Facility .	51%	livity	Clease.	TableHouse	Description	Weppert Link	Telm:	AUTTR-HTT
Senice	Endress & Hauser	Neutretay	delfast.	Overtil	Taok III	Claut2	22/08/2016			Sale Getected	2
Sensor	Endvers & Houser	Nivotester	Belfast	Overfill	Tack 45	Client2	22/08/2016	Report 4324		Safe-condetected	6
Skrode	Enthesis & theseler	Neobertal	DeTest	Overfill	Tarris 30	chents	12/05/2016	Report 3343		Safe chidetected	1
Sensor	Endreus & Hauser	Nexpenter	Reifast	Overfill	Tank 30	(Direct2	10/08/2016			Safe Detected	
Sensor	Endvets & Hauser	Liquiphent	Boltast.	Overfill	Torik 98	Glent2	23/86/2016	Report 2233	RPTS/Report 1233	Dangerous Undet	÷
Semor	Endress & Hauser	Nivoteitie	delfest	Overfall	Tank 3	Client2	04/08/2016	54		Dangarous Datact	5
Sensce	Etabreta & Hauter	Lepiphant	Belfast	Overtill	Terk 18	Clauda	72/08/2016			Safe Detected	1
Sensor.	Endress & Hauser	Liquiphant	8etas	Overfill	Tark 22	Olent2	22/06/2016			Safe Undetected	3.
Sensor	Endress % Heuser	Liquiphant	Belfast	Overfill	Tarik 49	id4ent2	15/08/2016	Report 3212		Dangerous Detect	
Senior	Endress & Hauser	Dquiphant	Selfast	Operation	Tank 40	(Client2	15/08/2016	Report 1234		Safe Undetected	2
Sensor	Endness & Hausen	Liquiditient	Belfast	Over fill	Tank 41	(Gient2	32/04/2016	Report 3363.		Sate Detected	8
Sensor	Endress & Heuser	Elquiphant	Belfast	OverBl	Tank 41	Cinet2	16/08/2013	Axport 3363		Safe Outected	1
Secura	Endreis & Hauser	Equiphant	Selfast	Overtill	Tank 40	Client2	04/04/2016	Report 3357	8P17/8eport 1357.	Safe Detected	1
Sensor	Endvers & Houser	Nivobester	Belfast	Overfill	Tack 41	Olent2	16/08/2016	Report 1342		Dangerous Detect	1
Sensor	Endress & Hauser	Liquiphant	Belfast	Overfill	fami 50	(dwntz	13/08/2016	(keport 1214	APTIV/Export 1234	Dangerous Unded	1
Senior	Endrines & Houser	Liquiphant	Settant	Overfill	Tank 30	(Direct2	22/08/2016			Safe Detected	2
Sensor	Endrets & Hauser	L'iquiphant	Boltast.	Overfill	Taok 27	Glent2	17/08/2036			Safe Winketertert	÷



P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 35 OF 50

4.3.2.8 Configuration Management

Although configuration management is more specific to manufactures of components and software development of the SIS, there is a requirement for end users to control changes with respect to maintaining continuity of the system by ensuring traceability of any changes throughout the SIS lifecycle.

In the case of NuStar which utilise programmable logic solvers this entails control of updates of the safety plc code – version numbers – traceability and audibility of changes Sensor change – like for like? – Firmware version – Serial Number

ACTION 2016 - 11 - A letter to be sent to PILZ asking them to provide information on how the control version and Cyber Security of the logic solver software for NuStar.

4.3.2.9 SIS Security

End Users shall develop and conduct a risk assessment;

An example for achieving this could be:

- Identify all threats;
- Assign a risk level to each threat;
- Assess the consequence of each threat;
- Identify where vulnerabilities lie;
- Review adequacy of current protection measures;
- Plan and implement additional protection measures.

NuStar Energy have already recognised the importance of not only SIS security but also that of the BPCS. Action 2016 - 08 is already in place to risk assess the SIS and associated control systems.

See Also ACTION 2016 – 11.




4.4 SIS Testing, planning, results, data collection and analysis.

Testing Schedule:

Terminal	Last Test Done	Scheduled Next Test
Belfast	11 th May 2016	April 2017
Dellast	Valve closure times are shown within the testing document for 90 seconds. This is applied to all valves and may only be required on Dockline valves. During the testing many valves closed quicker. ACTION 2016 – 12: Confirmation of correct valve closure times and update of testing document. Further corrosion identified on liquiphants. Tank 9 was not wet tested due to sticking collar. Tamper proof labels – See 4.4.1 Tank 46 & 47 are in-accessible so testing was performed per channel as opposed to in the head of	
	the device	
Clydebank	24 th October 2016 It was observed that Tank 6 was on Road off-loading and the SRS shows it as dockline import. This modification was done several years ago. ACTION 2016 - 13: Update SRS to reflect Tank 6 current operation. It was brought to the attention of the safety committee that a pump control system is within the software of the SIS plc and that it is not tested. ACTION 2016 – 14: Update the SRS to reflect the SIS interface with pump 41. ACTION 2016 – 15: Tank 22 Temperature is within the SIS, this is not within the SRS. It is no longer required as no exotherm possible. It was decided to add it to the SRS rather than remove it from the SIS application software.	November 2017
Eastham	8 th August 2016 Some ESV's have an override facility on top of the valve, following testing it appears that this facility can lock in the air and prevent the valve closing. ACTION 2016 - 16: The override lever to be removed from the ESV's. ACTION 2016 – 17: NuStar to investigate the override on DL3 with a view to removal or locking off.	July 2017
Grangemouth	10 th February 2016	February 2017
	Sensor heights confirmed. Labels missing.	-
Grays	21 st April 2016 See 4.8.2	April 2017

P & I DESIGN

4.4.1 Tamper Proof Labels Review



Tamper Proof Labels Review

Attachment method and usage not consistent across all terminals. NuStar wish to retain. Need a procedure to justify why a label may of been tampered will or else proof test will mark down as possible unauthorised modification. Agree attachment method, e.g. label across lid etc

Following discussion this was converted into an action:

ACTION 2016 - 19: Tamper Proof Labels Review

4.5 Training requirements and roles and responsibilities of employees and contractors.

Future training requirements: Eastham require a training for new operators. Training of Audits as discussed in Section 4.3.2.6.2.

ACTION 2016 - 07: Date to be agreed for Eastham training course. ACTION 2016 - 10 - Arrange IEC61511 appreciation training for auditors.

4.6 Review of organisation and resources.

There have been no changes to the organisation and resources and NuStar Energy feel that management of the systems is satisfactory.




4.7 Outcome of Functional Safety Assessments and Outstanding Action status.

See Section 2 for actions from current functional Safety Assessments.

4.8 Review of any management of change or modifications to the systems.

4.8.1 Eastham SIS



The committee discussed the number of modifications required to the SIS at Eastham, often resulting in one modification impacting on another. It was further established that in order to complete the Chloroform project a new logic solver would be required, as the existing cannot handle the analog inputs.

It was agreed to consider a simplification of the SIS, such that any tank IHLA would close all dockline valves. This should remove a lot of the requirement for modification to the SIS.

ACTION 2016 – 18: Eastham SIS simplification.



4.8.2 Grays SIS



Following discussion and checking with site who confirmed that the tank had been on FAME duty but was now empty.

An action was raised to establish future plans for this tank.


ACTION 2016 – 20: Grays converted water tank reused as product tank SIS?



- 4.9 Review of any HSE or other agency visits.
- 4.9.1 Competent Authority Visits

No other HSE visits have taken place.

4.9.2 TSA Safety Alert



The Safety Committee reviewed the TSA safety alert, then considered if this event could occur on any of their SIS.

It was confirmed that no NuStar SIS utilise a two-solenoid philosophy.



🔿 Navigator

NAVIGATOR TERMINALS SAFETY FLASH

Incident: Failure of SIS System During Test

Incident Date:	04" Nov 2016
Time:	15:00
Location:	Navigator Terminals Seal Sands


Brief account of the incident:

A SIS tank inlet valve failed to closed when commanded to do so from the SCADA control system. The control room operator requested maintenance to investigate the fault, the maintenance technician who investigated the fault could not close the valve, he isolated the nitrogen supply to the valve and the valve remained open, he then activated the tank high level trip to try and close the valve, the valve still failed to close.

An investigation into the failure was carried out and the fault was identified as a failure of the control solenoid valve. The solenoid valve shuttle had jammed preventing release of the nitrogen through the solenoid valve vent port, this prevented the actuator from closing the valve.

The diagram below shows the design of the SIS valve control and SIS solenoids. The control solenoid is nearest the valve actuator and the SIS solenoid is remote from the actuator. This design caused an indirect failure of the SIS due to the failure of the control solenoid valve.

It is clear that if the SIS solenoid valve was installed nearest the actuator this failure would not have resulted in failure of the SIS.



P & I DESIGN

P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 42 OF 50 4.10 Review of any changes in the standard or competent authority guidelines.

IEC 61511:2016 has now been released in provisional format.

NuStar Energy Safety Committee will now work to the guidelines of IEC 61511:2016.


4.11 Review of competency requirements.

NuStar Energy feel that the competency of those working on the SIS systems is currently acceptable and will be reviewed in line with any additional guidelines or changes in the standard. See also 4.3.2.1.

4.12 Review of independent Instrumented Safety Functions.

NuStar Energy have maintenance agreements in place with manufactures/suppliers of their BPCS.


4.12.1 Clarification of non-SIS functions in SIS Safety PLC



See Action 2016 – 14.



5 ACTIONS ARISING FROM THIS MEETING





P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk

	- 10 - Arrang	e IEC61511 ing for auditors.
Descriptio		
David R	30 Dec	00800
NuStar Safety (Committee Meetin	30th November ~









P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 46 OF 50


NuStar Safety C	30 Dec	30th November ~
		the SRS to erface with pump
David F	30 Dec	06800
Tank22 Te SRS. It is n	mperature is within ti o longer required as	30th November ~ 2 Temperature he SIS, this is not within the no exotherm possible. It was
	add it to the SRS rat	ther than remove it from the SIS
NuStar Safety C	er 💮 30 Dec	00000
	16: The over ed from the	rride lever to be ESV's.

SomeESV's have an override facility on top of the valve, following testing itappears that this facility can lock in the air and prevent the valve closing.




P & I Design Ltd 2 Reed Street, Thornaby, UK, TS17 7AF Tel: + 44 (0)1642 617444 Fax: + 44 (0)1642 616447 www.pidesign.co.uk


DOCUMENT NO: NU001115_MIN ISSUE: B DATE: 01.12.16 PAGE 47 OF 50











6 DATE OF NEXT MEETING

08.00 - 10th May 2017 at Grays Terminal.

P & I DESIGN

Signature Certificate

Document Reference: V2T4MKI3SJLYMWPUIH7FIP

RightSignature

Easy Online Document Signing



David Ransome Party ID: 5NJT8JJN33KUT4FGFZREBS IP Address: 86.14.218.30 VERIFIED EMAIL: drr@pidesign.co.uk



Multi-Factor Digital Fingerprint Checksum

11bf3a34c02278dec9abd25d4c5da947326ac007

III BER EVENESERE BER KARZHARA HARTING.

Timestamp

	Audit	

2016-12-01 02:55:26 -0800	All parties have signed document. Signed copies sent to: David Ransome and P
	I Design Ltd.
2016-12-01 02:55:26 -0800	Document signed by David Ransome (drr@pidesign.co.uk) with drawn signature
	86.14.218.30
2016-12-01 02:53:52 -0800	Document viewed by David Ransome (drr@pidesign.co.uk) 86.14.218.30
2016-12-01 02:53:35 -0800	Document created by P I Design Ltd (signature@pidesign.co.uk) 86.14.218.30

